

Indicator CSS



Operating manual **- Translation of the original -** (keep for future use)

Version 2.0

Date: 2023-11-28



Bosche GmbH & Co. KG

Reselager Rieden 3
D-49401 Damme

Phone +49 5491 999 689 0
Fax +49 5491 999 689 9
Email info@bosche.eu
Web www.bosche.eu

This manual has been created on: 2023-11-28

Copyright

Bosche GmbH & Co. KG retains all rights for this document.
Copying, disclosure to third parties or use of its contents are
forbidden without our express approval

© 2023

Foreword

These operating instructions provide you with detailed information about the Indicator CSS.

These instructions contain safety instructions to guarantee safe use of the volume and weight measurement system.

The manufacturer strives to improve their products on an ongoing basis. They reserve the right to carry out any and all modifications and improvements that they consider to be necessary. However, this means that there is no obligation to carry out retrospective modifications in this connection.



Danger

Before using the Indicator CSS, you must have read and understood the operating instructions and the safety regulations that they contain.



Note

Errors and omissions in the documentation reserved. If necessary, please inform Bosche GmbH & Co. KG of any errors in the documentation. We would also be grateful for any suggestions for improvements that you may have.

The manufacturer's contact data is listed on the reverse of the title page. If you have any queries or problems, please contact the manufacturer without delay.



Note

Have your serial number to hand when contacting Bosche GmbH & Co. KG.

Table of contents

1 Safety	4
1.1 For your safety	4
1.1.1 General	4
1.1.2 Safety symbols in this manual.....	5
1.2 Intended use	5
1.3 Obligations of the owner/user	6
1.4 Obligations of the operator.....	6
1.5 Description of the dangers	6
1.5.1 Danger of injury.....	6
1.5.2 Danger of damages.....	6
1.6 Liability and warranty	6
2 Description	7
2.1 Layout	7
2.2 Display	8
2.2.1 Display overview	8
2.2.2 Legend for the weighing value display	9
2.3 Keyboard overview.....	10
3 Transport, commissioning/start-up and tests/inspections	11
3.1 Control.....	11
3.2 Packaging and disposal	11
3.3 Regular inspections/checks	11
3.4 Testing equipment monitoring.....	11
3.5 Extraordinary inspections.....	12
3.6 Repair work	12
3.7 Use other than the intended.....	12
3.8 Commissioning / start-up	13
4 Operation	14
4.1 Switching on and off.....	14
4.1.1 Switching on.....	14
4.1.2 Switching off.....	14
4.2 Weighing process.....	15
4.3 Control weighing	15
4.3.1 Switching on and off the three-colour signal light.....	15
4.3.2 Setting the limit.....	15
4.4 Different memories.....	17
4.4.1 Short-term sum memory	17
4.4.2 Long-term memory.....	17
4.5 Automatic switch-off.....	19
4.6 Reset to zero	19
4.7 Zero tracing	20
5 Settings	21
5.1 Main menu	21
5.1.1 Adjustment with weight	21
5.1.2 Theoretical adjustment.....	25
5.1.3 Adjustment correction	29
5.1.4 Reset to factory-settings	29
5.1.5 Setting the time and date	31
5.2 Quick selection menu.....	33
5.2.1 Setting the background lighting.....	33

6 Troubleshooting	36
6.1 In the event of a malfunction	36
6.2 Error messages of the scales	36
6.3 Customer service contact data	36
6.4 Information for the contact to the customer service	37
7 Technical data	38
7.1 Type plate	38
7.2 Technical data	38
7.3 Technical drawing	39
7.4 Scope of delivery	39
8 Menu overview	40
8.1 Navigation in the menu	40
8.2 Function menu overview	40
8.3 Menu protected by a password	43
8.4 Quick selection menu (HLG menu)	47
9 Declaration of Conformity	50
9.1 Declaration of Conformity for non-verified scales	50

1 Safety

This chapter warns against possible risks when handling the device. The information for detection of risks contained in this chapter is intended to allow the safe and correct operation.



It is important to read and adhere to this operating manual and particularly this chapter prior to operating this device.

1.1 For your safety

1.1.1 General

In addition to safety information, the operating manual includes:

- A general product description
- Information about installation and connection of the device
- Instructions to operate the device
- Maintenance and care instructions
- Troubleshooting and remedy instructions
- Technical data

Always keep this operating manual and additional documents for your personnel at hand in the direct vicinity of the device.

Always adhere to all information, notes, instructions and explanations contained in this manual! Avoid accidents caused by incorrect operations! Also adhere strictly to the valid legal regulations in addition to the safety instructions specified in this manual.

Prior to commissioning/start-up read the safety information/instructions and familiarise yourself with dangerous areas.

The device is constructed according to the current state of art and the valid safety regulations. However, there are risks in the event of incorrect operation or non-observance of the safety regulations:

- Danger to limb and life of operators, third persons and animals staying in the vicinity of the device.
- Danger to the device and other assets of the owner/user
- Danger to the efficient operation of the device.

1.1.2 Safety symbols in this manual

The following symbols are used on all important positions in this manual. Particularly observe these notes and treat very careful.



Danger

This note indicates danger of injuries and/or danger to life, if specific behaviour rules are not observed.

When this symbol appears in the operating manual, please take all required safety measures.



Attention

This note warns against damage to assets as well as financial disadvantages and responsibility under criminal law (e.g. loss of the warranty, cases of third party risks, etc.).



Note

Important notes and information about an efficient, economic and environmental friendly handling are specified here.

1.2 Intended use

The Indicator CSS exclusively serves to display the weight in combination with suitable load cells.

Any further use is considered as not in accordance with the intended use. The manufacturer does not assume any liability for resulting damage.

The intended use also includes:

- Observance of all notes, information, instructions contained in the documentation as well as in all supplied manuals issued by the manufacturer.
- Adherence of the maintenance and service conditions and intervals prescribed by the manufacturer and
- Observance of the technical data.

Adhere to the attendant accident prevention regulations as well as other generally approved technical safety rules.



Note

Always specify the serial number of your display for all questions, orders or jobs. This will facilitate the communication with the manufacturer and prevents error during editing your request.

1.3 Obligations of the owner/user

The owner/user obligates himself to only instruct persons to work on the device, who:

- Are familiar with the basic rules concerning safety and accident prevention and are trained in the operation of this device and
- have read and understood the operating manual, the safety chapter as well as the warning notes.

1.4 Obligations of the operator

All persons instructed to operate the device obligate themselves:

- to always ensure the safety of other persons,
- to read the operating manual, the safety chapter and the warning notes and
- to only operate the device when they are familiarised with its functions.

1.5 Description of the dangers

1.5.1 Danger of injury

- Always switch off the device for care and maintenance work.
- Never insert any pointed objects into the electric contacts.
- Do not change the contacts.
- Stop device operation, if the device or the connection line is damaged or have a malfunction.

1.5.2 Danger of damages

- Only connect the device to suitable load cells (see chapter 7.2 "Technical Data").
- Never use pointed objects to actuate the device keys.

1.6 Liability and warranty

The BOSCHE company offers a restricted warranty for components, which became faulty due to strain or material faults. The warranty starts with the date of delivery. The BOSCHE company retains the right to repair or replace components. Repair work executed during the warranty period will not extend the period of warranty. The warranty becomes null and void:

- In the event of incorrect use / use other than the intended use or incorrect installation
- Incorrect electric connection
- Use of an incorrect or non-licensed analogue / digital converter
- Non-observance of the specifications in the operating manual
- Conversion, modification or opening of the device
- Unintentional or mechanical damage and damage caused by media, liquids, natural wear.

2 Description

2.1 Layout

The Indicator CSS is a control system and display used to operate an animal scales and to determine the weight of animals. The weighing results can be saved or transmitted.

An integrated three-colour signal light optically supports product weighing.







Item	Designation
1	Integrated three-colour signal light (red: Weight too high, green: Admissible weight, yellow: Weight too low)
2	Housing
3	Cable glands
4	Wall holder

2.2 Display

The displays of the individual animal scales (ETW) series offers all advantages of quick and accurate weighing. The keyboard is water-proof and the LCD displays are equipped with background lighting as a standard. All displays have a zero function, a three-colour signal light and a sum memory, which allows saving of individual weighing processes and invoking them as a total sum.

2.2.1 Display overview



W1	Scale 1
→0←	Zero setting, sets the zero point for all following weighing operations. Zero is displayed
G	Gross weighing (english)
	Animal weighing function
	Stability indicator lights up when a weight is stable.
	Unstable indicator, lights up when a weight is in motion.
kg	Active weight unit: [kg, g, t, lb]

2.2.2 Legend for the weighing value display








A	B	C	D	E	F	G	H	I	J	K	L	M
A	b	c	d	E	F	G	h	i	J	K	L	M

N	O	P	Q	R	S	T	U	V	W	X	Y	Z
n	o	P	q	r	s	t	u	v	W	X	y	Z

0	1	2	3	4	5	6	7	8	9
0	1	2	3	4	5	6	7	8	9

2.3 Keyboard overview



Key	User level	Function level
	The current weight on the scales is saved.	The activated number during parameter value setting or setting of other functions can be displaced to the left. 
	When a USB stick is connected, the data are transmitted to the stick. For this purpose, press the "MR_TRANSFER" key for two seconds. The sum of the saved individual weighing processes and the resulting total weight are displayed. To delete individual weighing results simultaneously press the keys "M+" and "MR_TRANSFER" (MC).	The activated number during parameter value setting or setting of other functions can be increased. 
	If the keys "LIMIT" and "ON/OFF_TARE" are actuated simultaneously, the saving process is cancelled.	Apply the input during parameter value setting or setting of other functions.  ENTER
	Used to switch on and off the display device. For switch off, press the key "ON/OFF_TARE" for two seconds, OFF appears in the display.	Leaving the function level. ESC

3 Transport, commissioning/start-up and tests/inspections

3.1 Control

When the display is delivered, check the packaging, the device and possible accessories for visible damages.

3.2 Packaging and disposal

Keep all parts of the original packaging for a possible return.



Note

Only use the original packaging, if the display is returned.
Prior to the transport, disconnect/fasten all loose/moving parts of the device.
Secure the parts against slipping/damage.

Dispose of the packaging and the display according to the national and/or local regulations by law valid on the installation site. Separately dispose of a defective battery according to the national and local regulations on environmental protection and recycling.

Do not treat a battery as standard waste. Please dispose of via a waste management company.

3.3 Regular inspections/checks

Check the display for visible damage, prior to each use. Also check electric lines for damage, prior to each use. If defectives can be detected, immediately stop operating and any other work on the display or the electric lines and contact an authorised expert.

3.4 Testing equipment monitoring

Quality assurance requires regular inspections of the technical measuring features of the display in connection with the scales and a possible available test weight. The owner/user can define a suitable interval as well as the scope of these inspections.

3.5 Extraordinary inspections

After special incidents, the display must be additionally inspected visually by an authorised person (even if not within the regular inspection interval).

Inspection criteria

- Correct function of the display.
- Damages to the housing.
- Damages to electric lines and connectors.

If defectives can be detected, immediately stop operating and any other work on the display or the electric lines and contact an authorised expert.

3.6 Repair work

Only the manufacturer or persons instructed by the manufacturer are allowed to carry out repair work on the display.

The electronic components are not completely water-proof and must not come into contact with splash water or being immersed. If the electronic components become wet or visible damages can be detected, stop operating the scales.

If spare parts or accessories are required, please contact your supplier.

3.7 Use other than the intended

- Protect the electronic display unit against humidity.
Particular protection is required during cleaning work.
- If small amounts of the goods to be weighed are removed or added, incorrect weighing results might appear caused by the “Stability compensation” integrated in the scales!
- Never modify the design of the display. This can lead to incorrect weighing results, technical safety defects as well as the destruction of the display.
- Only use the display in accordance with the described specifications



Danger

**Never operate the display in potentially explosive atmosphere.
The display is not explosion protected.**

- Only use original spare parts.




Attention

The design/construction of the product as well as all regulations (standards, etc.) specified in the operating manual refer to the directives valid in Germany. Only use the product in other countries in accordance with the directives, regulations and laws valid in the country of use.


Only use original spare parts!

3.8 Commissioning / start-up


Keep the device clean and do not expose to an environment influencing the display accuracy.




Protect against draught!



Protect against heat,
sun and frost!



Protect against tilting ;
and vibration!



Avoid unstable
voltage sources!



Avoid humidity!

Observe the following, prior to commissioning/starting up:

Ensure that the weight on the scales does not exceed the maximum load!



Note

Allow a short heat-up time to stabilise the display (approx. 15 minutes).



Note

Ensure that a 230 V AC voltage supply is available on the installation site (unless operation with rechargeable batteries is intended).

4 Operation

4.1 Switching on and off

4.1.1 Switching on




- Press the key (4) “ON/OFF_TARE”.
 - The display is switched on.
 - The software version is displayed.
 - Then a display self test is made and the scales automatically sets to “0.0”.
- The display has an automatic function to reset the scales to zero. If the scales displays small numbers, press the key (4) “ON/OFF_TARE”. Weighing starts at zero.

4.1.2 Switching off

- Press the key (4) “ON/OFF_TARE” for two seconds.
 - “oFF” appears briefly in the display.
 - The display is switched off.

4.2 Weighing process

- Place the goods to be weighed on the weighing platform. For animals: Wrangle the animals into the scales.
 - The stability display appears with stable values 



- If the goods to be weighed are heavier than the set weighing range, "E.OLP" (= overload) appears on the display.



4.3 Control weighing

The control weighing can be used to check the weight of individual animals. The three-colour signal light additionally indicates whether or not the weighed animals are too light or too heavy.

4.3.1 Switching on and off the three-colour signal light

- Press the key (3) "LIMIT" for two seconds.
 - The status of the three-colour signal light briefly appears on the display.
 - Status "ON": The three-colour signal light is activated.
 - Status "OFF": The three-colour signal light is deactivated.

4.3.2 Setting the limit

- Briefly press the key (3) "LIMIT".
 - The message (LOW) appears on the display:



- Briefly press the key (3) "LIMIT" again.
 - The display changes over to the value input.

- The RH display flashes.



- Enter the lower tolerance value. If the weight is higher, the three-colour signal light is green. If the weight is lower, the three-colour signal light is yellow.
- Press the key (2) <UP> to adjust the value.
- Press the key (1) <LEFT> to go on by one digit to the LH side and adjust the value.
- Actuate the key (3) <ENTER> to confirm the lower tolerance value.

- This message briefly appears in the display:



- The message (HIGH) appears on the display:



- Briefly press the key (3) < ENTER> again.
 - The display changes over to the value input.
- Enter the upper tolerance value. If the weight is higher, the three-colour signal light is red.
- Proceed in the same manner as for the "LOW" entry.
 - Then the display automatically switches to weighing mode.

4.4 Different memories

4.4.1 Short-term sum memory

- Press the key (1) “M+” to save the current weight.
 - The current weight is displayed.
 - Ensure that the scales always returns to “0” (zero) (the symbol **→0←** appears on the display) before the next weight can be added to the memory.
- Press the key (2) “MR-TRANSFER” for two seconds.
 - The number and sum of the saved weighing results appear.
 - Then the display automatically switches to weighing mode.
- Simultaneously actuate the key (1) “M+” and key (2) “MR-TRANSFER” to delete the sum memory.
 - Once deleted, the weighing results cannot be restored.

4.4.2 Long-term memory

All weighing results are saved in the long-term memory. The long-term memory can be transmitted to a USB stick. Then it is available as .csv file for evaluation on a computer.

- Connect the USB stick.
 - The message “USB In” appears on the display.
 - The star symbol appears on the right of the display, i.e. the USB stick can be used.
- Briefly press the key (2) “MR_TRANSFER”.
 - The data from the long-term memory is transmitted to the USB stick.
- Remove the USB stick and connect it to a PC.
 - The USB stick contains the folder “BOSCHE”.
- Open the “BOSCHE” folder.
 - The .csv file(s) contain(s) the weighing results of the individual days. All weighing results of one day are in this case (main menu/USB/Single) automatically grouped in one file.
 - The file can be opened with Microsoft Excel or the text editor.

The following data is transmitted:

1st Consecutive number of the weighing process (alibi No.).

2nd Date

3rd Time

4th Gross weight in kg

5th Tare

6th Net

7th Weight unit

Deleting the long-term memory

- Press the key (1) “M+” for two seconds.
 - The message (High-Low-Go-Mode) appears on the display:

The LCD display shows the message "H L o G o" in a segmented font, enclosed in a rectangular border.

- Press the key (2) “MR_TRANSFER”.
 - The message (memory) appears on the display:

The LCD display shows the message "M E m o r y" in a segmented font, enclosed in a rectangular border.

- Press the key (3) “LIMIT”.
 - The display shows the message (Clear alibi memory):

The LCD display shows the message "C L r . A l b" in a segmented font, enclosed in a rectangular border.

- Press the key (3) “LIMIT”.
 - The display shows the message (Clear No):

The LCD display shows the message "C L r . N o" in a segmented font, enclosed in a rectangular border.

- Press the key (2) “MR_TRANSFER”.
 - The display shows the message (Clear Yes):

The LCD display shows the message "C L r . Y E S" in a segmented font, enclosed in a rectangular border.

- Press the key (3) "LIMIT".
 - The display shows the message (Clear done):



- The long-term memory is deleted.
 - The message "Memory" appears again on the display.
- Press the key (4) "ON/OFF_TARE".
 - The display automatically switches to weighing mode. The weighing process can take place as usual.

4.5 Automatic switch-off

The display has an automatic switch-off function. The time period can be set between 1 and 99 minutes. The automatic switch-off becomes active, if the weight does not change on the platform or weighing bridge during the set time period. The automatic switch-off is deactivated as a standard and must be activated in the quick menu. For an overview and detailed explanations of the quick menu, please refer to the chapter "Quick menu A06-01 - AU off (Automatic switch-off)".

4.6 Reset to zero

The display has an automatic function to reset the scales to zero to compensate for minimum deviations caused by the environment or soiling on the scales. However, it might be possible, that low values appear on the display although the platform is empty. The display can be reset to zero at any time using the key (4) "ON/OFF_TARE" to ensure that the weighing actually starts with zero.

The zero setting range can be selected +/- 0, 2, 4, 10, 20, 50, 100 % of the weighing range.

4.7 Zero tracing

The zero tracing function automatically corrects small deviations of the zero display. The range of the zero tracing can be set between the following values:

Off / 0.25d / 0.5d / 1d / 2d / 3d / 4d (up to max. 1 % of the maximum load)

The zero tracing function must be activated in the menu.

Zero tracing:

- is only active after the switch-on zero setting range.
- is active in both directions, positive and negative.
- operates actively up to the set limit.
- deactivates itself when the set limit is exceeded.
- reactivates itself once the load has been removed.

5 Settings

5.1 Main menu

5.1.1 Adjustment with weight

According to the basic physical weighing principle at the installation site, each scales must be adjusted to the conditions on site such as gravity acceleration, temperature, location, etc.

- Ensure that no load is on the scales.
- Switch on the scales using the key "ON/OFF_TARE".
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:

A rectangular LCD display showing the text "CON 1" in a digital font. The "1" is positioned to the right of "CON" with a small gap between them.

- Press the key <LEFT>.
 - The following message appears in the display:

A rectangular LCD display showing the text "Code" in a digital font.

- Press the key <ENTER>.
 - The message "- - - -" appears on the display.
- Enter the code "0000" using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the code using the key <ENTER>.
 - The message (setting) appears on the display:

A rectangular LCD display showing the text "SET 1179" in a digital font. The "1179" is positioned to the right of "SET" with a small gap between them.

- Press the key <UP>.
 - The message (CAL/calibration) appears on the display:

A rectangular LCD display showing the text "CAL" in a digital font.

- Press the key < ENTER>.
 - The message (SPAN/two-point calibration) appears on the display:

A rectangular digital display showing the word "SPAN" in a stylized, segmented font.

- Press the key < ENTER>.
 - The message (Raw/raw measured value) appears on the display:

A rectangular digital display showing the word "RAW" in a stylized, segmented font.

- Press the key < ENTER>.
 - The current raw measured value of the A/D converter appears on the display:

Example 

- Press the key <ENTER> or <ESC>.
 - The message (Raw/raw measured value) appears again on the display:

A rectangular digital display showing the word "RAW" in a stylized, segmented font.

- Press the key <UP>.
 - The message (Zero) appears on the display:

A rectangular digital display showing the word "Zero" in a stylized, segmented font.

- Press the key < ENTER>.
 - The current raw measured value of the A/D converter appears on the display.

Example 

- Ensure that not load is on the scales.

- Briefly wait (until the displayed value hardly changes) and then confirm the value with the key <ENTER>.
 - The message “donE” briefly appears on the display.
 - The message (Zero) appears again on the display:



- Press the key <UP>.
 - The message (Load/load weight) appears again on the display:



- Press the key < ENTER>.
 - The currently set value of the load appears flashing on the display.
- Enter a value for the load using the keys <UP> and <LEFT>:
:

Example 

- Confirm the value using the key <ENTER>.
 - The current raw measured value of the A/D converter appears on the display.

Example 

- Ensure that the set load is on the scales.
- Press the key < ENTER>.
 - The message “donE” briefly appears on the display.
 - The message (Load/load weight) appears again on the display:



- Press the key <ESC> repeatedly to leave the menu.

- The message (Save ?) appears on the display:



- Press the key <ENTER>, if the value is to be saved.
 - The messages “donE” and “off” briefly appear on the display.
 - The scales is switched off.
- Press the key <ESC>, if the value is not to be saved
 - The message “off” briefly appears on the display.
 - The scales is switched off.

5.1.2 Theoretical adjustment


- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'CON 1' is displayed in a white, segmented, digital font. 'CON' is on the left and '1' is on the right, with a small gap between them.

- Press the key <LEFT>.
- The following message appears in the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'Code' is displayed in a white, segmented, digital font.

- Press the key <ENTER>.
 - The message “- - - -” appears on the display.
- Enter the code “0000” using the keys <UP> and <LEFT>.
- Confirm the code using the key <ENTER>.
 - The message (setting) appears on the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'SET 179' is displayed in a white, segmented, digital font. 'SET' is on the left and '179' is on the right, with a small gap between them.

- Press the key <UP>.
 - The message (CAL/calibration) appears on the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'CAL' is displayed in a white, segmented, digital font.

- Press the key <ENTER>.
 - The message (SPAN/two-point calibration) appears on the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'SPAN' is displayed in a white, segmented, digital font.

- Press the key <UP>.

- The message (theoretical calibration) appears on the display:

A digital display showing the text 'nU-U' in a monospaced font, enclosed in a rectangular border.

- Press the key < ENTER >.
 - The message (field calibration/calibration with known load cells) appears on the display:

A digital display showing the text 'FIELD' in a monospaced font, enclosed in a rectangular border.

- Press the key < ENTER >.
 - The message (sensitivity) appears on the display:

A digital display showing the text 'SENS' in a monospaced font, enclosed in a rectangular border.

- Press the key < ENTER >.
- Enter a value using the keys < UP > and < LEFT > for the load cell sensitivity.

Example

A digital display showing the text '38550' in a monospaced font, enclosed in a rectangular border.

- Press the key < ENTER >.
 - The message "donE" and the following message briefly appear on the display again:

A digital display showing the text 'SENS' in a monospaced font, enclosed in a rectangular border.

- Press the key < UP >.
 - The message (maximum load) appears on the display:

A digital display showing the text 'LCAP' in a monospaced font, enclosed in a rectangular border.

- Press the key < ENTER >.

- Enter a value using the keys <UP> and <LEFT> for the maximum capacity of the load cell.

Example 

- Press the key < ENTER>.
 - The message “donE” and the following message briefly appear on the display again:



- Press the key <UP>.
 - The message (Zero) appears on the display:




If necessary, a new zero point of the scales can be adjusted here.

- Press the key < ENTER>.
 - The current raw measured value of the A/D converter appears on the display:

Example 

- Press the key < ENTER>.
 - The message “Wait” (Wait) briefly appears on the display and the message(Zero) again:



- Press the key <ESC> twice to leave the menu.
 - The message (gravity/gravity factor) appears on the display:



If necessary, the gravity factor (gravity acceleration) can be adapted here.

- Press the key < ENTER>.
 - The value for the gravity acceleration appears on the display.

A digital display showing the value 98.1276 in a segmented font.

- Enter the value for the gravity acceleration of the respective installation location here.
- Press the key < ENTER>.
 - The message “donE” and the following message briefly appear on the display again:

A digital display showing the message Gr AccY in a segmented font.


- Press the key < UP>.
 - The message (calibration method) appears on the display:

A digital display showing the message CALSEL in a segmented font.

- Press the key < ENTER>.
 - The calibration method (field) activated last appears on the display:

A digital display showing the message FIELd in a segmented font.

- Press the key < UP>.
 - The message (Factory) appears on the display:

A digital display showing the message FActrY in a segmented font.

- Press the key < UP>.

- The message (SPAN) appears on the display:

A digital display showing the word "SPAN" in a stylized, segmented font, enclosed in a rectangular border.

- Actuate the key <ENTER> to activate the desired calibration method.
 - The message "donE" briefly appears on the display.
 - The message (calibration method) appears again on the display:

A digital display showing the word "CALSEL" in a stylized, segmented font, enclosed in a rectangular border.

- Press the key <ESC> repeatedly to leave the menu.

5.1.3 Adjustment correction

If the displayed value of the theoretical adjustment (factory-set default value) deviates from the value of the real weight, this value can be corrected.

- Simultaneously actuate the keys <UP> and <LEFT> for approx. three seconds.
 - The RH digit of the displayed weight starts flashing.
- Correct the value using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the value using the key <ENTER>.
 - The message "donE" briefly appears on the display.

This correction can be repeated as often as required.

5.1.4 Reset to factory-settings

- Switch on the scales using the key "ON/OFF_TARE".
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:


A digital display showing the word "CON" followed by a space and the number "1", all in a stylized, segmented font, enclosed in a rectangular border.

- Press the key <LEFT>.

- The following message appears in the display:



- Press the key <ENTER>.
 - The message “- - - -” appears on the display.
- Enter the code “0000” using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the code using the key <ENTER>.
 - The message (setting) appears on the display:



- Press the key <UP> four times.
 - The message (reset) appears on the display:



- Press the key <ENTER>.
- Use the <UP> key to navigate.
 - The messages “ON” or “OFF” appear on the display.
- Actuate the “ON” message using the <ENTER> key.
 - The display is reset to factory-settings.

**Attention**

When the system is reset to factory-settings all settings made after delivery will be lost!

5.1.5 Setting the time and date

The scales is equipped with an internal clock.

- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:



- Press the key <UP> three times.
 - The message (Time) appears on the display:



- Press the key <ENTER>.
 - The message (hour) appears on the display:



- Press the key <ENTER>.
 - The value currently set appears on the display and starts flashing.
- Correct the hours using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Min.” value.
- Correct the minutes using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Sec.” value.
- Correct the seconds using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Day” value.

- Correct the days using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Month” value.
- Correct the months using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Year” value.
- Correct the year using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The message “donE” briefly appears on the display.
 - The message (Time) appears again on the display:

A digital display showing the word "Time" in a monospace font. The letters are white on a black background, and the display is enclosed in a thin black rectangular border.

- Press the key <ESC>.
 - The message (Save ?) appears on the display:

A digital display showing the text "SAVE ?" in a monospace font. The letters are white on a black background, and the display is enclosed in a thin black rectangular border.

- Press the key <ENTER>, if the value is to be saved.
 - The messages “donE” and “off” briefly appear on the display.
 - The scales is switched off.
- Press the key <ESC>, if the value is not to be saved.
 - The message “off” briefly appears on the display.
 - The scales is switched off.

5.2 Quick selection menu

5.2.1 Setting the background lighting

- Ensure that no load is on the scales.
- Switch on the scales using the key "ON/OFF_TARE".
- Press the key <LEFT> for two seconds.
 - The message (High-Low-Go-Mode) appears on the display:



- Press the key <UP> five times.
 - The message (Display) appears on the display:



- Press the key <ENTER>.
 - The message (Background lighting) appears on the display:



- Press the key <ENTER>.
- Use the <UP> key to navigate.
 - The message (Background lighting: Automatic/On/Off) appears on the display:



- Press the key <ENTER> when "bL AU" is displayed.
 - The time (seconds) for background lighting can be entered here.

- The message (Background lighting) appears on the display:

A digital display showing the text "BL 120" in a seven-segment font. The "BL" is on the left and "120" is on the right.

- Press the key <UP> several times.
 - The displayed value is changed (10 - 120). The time value "120" displays the seconds, for which the display (inactivity of weight) remains active.
- Press <ENTER>.
 - The message "donE" briefly appears on the display.
 - The following message appears again in the display:

A digital display showing the text "BL 19ht" in a seven-segment font. The "BL" is on the left and "19ht" is on the right.

- Press the key < ENTER>.
- Use the <UP> key to navigate.
 - Following messages appear on the display:

A digital display showing the text "bL AU" in a seven-segment font. The "bL" is on the left and "AU" is on the right.

A digital display showing the text "bL on" in a seven-segment font. The "bL" is on the left and "on" is on the right.

A digital display showing the text "bL off" in a seven-segment font. The "bL" is on the left and "off" is on the right.

- Press the key <ENTER> when "bL On" is displayed.
 - The background lighting is always ON.
- Press the key <ENTER> when "bL Off" is displayed.
 - The background lighting is always OFF.
 - The message "donE" briefly appears on the display.

- The following message appears again in the display:



- Press the key <ESC> repeatedly to leave the menu.

6 Troubleshooting

6.1 In the event of a malfunction

We recommend switching off the scales briefly and disconnecting it from the mains, if a malfunction occurs in the program sequence. Then restart the weighing process.

6.2 Error messages of the scales

Error message	Description	Possible cause
E.016	No USB stick connected.	No USB stick available.
E.040	No data for transmission available.	No values saved in the long-term memory.
--OL--	Overload	The maximum set weighing range is exceeded.
Err.Lin	Error Limit Hi and LOW values incorrectly defined.	The set HI value is smaller than the set LOW value.
ErrScL	After switching on and the display self test no digitalisation unit is detected. The scales do not switch to weighing mode.	The scales is not connected.
Er2Ero	The weight is not added to the sum memory during weighing.	The scales is not zeroed prior to the weighing process →0← .

If any other malfunctions or error messages occur, please switch off the scales and after a short while on again.

If error messages occur again, please contact the Bosche customer service.

6.3 Customer service contact data

Bosche GmbH & Co. KG
Reselager Rieden 3
D-49401 Damme

Phone +49 5491 999 689 0
Fax +49 5491 999 689 9
Email info@bosche.eu

6.4 Information for the contact to the customer service

Owner/user	Specifications
Name of your company	
Name of a contact person	
Contact data Telephone Fax Email	

Product	Specifications
Model name	
Serial number	
Type key	
Date of purchase	
Name and location of the supplier	



Note

Fill in the table shown above when the display is delivered to be able to use all information without any problems at any time.

Information about the problem:

Examples for required specifications to support troubleshooting:

- Does the display operate fault-free since its delivery?
- Has the display any contact to water?
- Was there any damage due to a fire?
- Was there a thunderstorm before / during the malfunction?



Note

Please inform us about the entire history of the display.

7 Technical data

7.1 Type plate


Example



7.2 Technical data

Feature	Value / Unit
Dimensions (W x H x D)	185 x 185 x 88 mm
Weight aluminium housing	Approx. 1.35 kg
Power supply (external)	240 V / 50 - 60 Hz
Max. resolution (depending on the weighing cells used)	External 1/30,000 Internal 1/1.000.000
Supply voltage (U_{exc})	5 Vdc
Minimum measuring signal per scale interval (ΔU_{min})	0,2 μ V
Lower limit of the load resistance (R_{Lmin})	87,5 Ω
Display	6 digits, LCD illuminated, digit height 30 mm
Keyboard	4 pressure point keys
Interfaces	RS232 optional: RS485, Lan, Bluetooth (optional)
Functions	Weighing value display, sum memory, presettable weighing with alarm, control signal lights
Number of load cells	Up to 4 load cells à 350 Ohm or 8 load cells à 700 Ohm.
Load cell sensitivity	1mV/V~3mV/V
AD converter	24 bits, 1 channel
Measurement rate	50 measurements per second
Zero input range	0mV~5mV
Signal input range	0mV~15mV
Settling time	2 seconds typical
Operating temperature	+5°C to +40°C
Relative air humidity	max. 80 %, non-condensing

7.3 Technical drawing



7.4 Scope of delivery

Component	Note
Indicator CSS	
Operating manual	
Wall holder	

8 Menu overview

8.1 Navigation in the menu

- A menu or subroutine is left by pressing the key <ESC>.
- The <UP> key is used to navigate between the individual menu points and modify editable numbers.
- The key <LEFT> serves to move the input cursor to the left by one digit.

8.2 Function menu overview

Actuate the <ENTER> key (or <LIMIT>) after the display has been switched on and while the countdown on the display counts down.

Menu	Subroutine	Options	Function
COM1	Mode 1	Off, CONT, ST1,ST2, STC, PR1, PR2, PR3, ASK	
		Cont (continuously transmits data)	
	Outp	PC // Bosche data string Print 1// Print 2 // HPP-250 Print 3 // LP-50 Print 4 // HPP-250 for HLS lifting carriages Print 5 // HP083 Remote display „rntdSP“// external large display (RD50, RD100, RD150, RD195) Lights // external three-colour light (PC0, PCL, PCG, PCH) (Status lamp SL3)	Protocol setting (Printer type)
	Baud 1	1200, 2400, 4800, 9600, 14400, 19200, 28800, 38400, 57600, 115200,	Data transmission speed (Baud rate)
	Part 1	8n1 //8 Data bytes, No Parity, 1 Stop Bit 7E1 // 7 Data bytes, Even Parity, 1 Stop Bit 701 //7 Data bytes, Odd Parity, 1 Stop Bit	Parity settings (for data transmission)
	Ntw.Rst	Network reset No Yes	The WLAN settings can be reset.

Menu	Subroutine	Options	Function
COM 2	As COM 1	As COM 1	As COM 1
USB	Multpl	// Alibi data blocks: the data blocks of all days are written in one file during saving on the USB stick.	Setting of the saving method of measured data on the USB stick.
	Single	// Alibi data blocks: an individual file is created for each measuring day during saving on the USB stick.	
Time	Hour, Min, Sec, Day, Month, Year		Setting of time and date.
FUNC	Units	SEL 0: no weight unit SEL 1: g (gram) SEL 2: kg (kilogram) SEL 3: t (ton) SEL 4: lb (pound)	Weight unit selection.
	Ext.Dev:	Off Gyro	“External Device” selection (is not used!).
SPEED	SMPLNG	6, 12, 25, 50, 100, 200	ADC sampling rate Sampling rate of the external ADC (Attention: The setting does usually not require any changes! Effect on the weight calculation!).

Menu	Subroutine	Options	Function
LEGAL	ALB.SW (Alibi Switch)	Al.On Al.Off	Saving weight data in the internal memory (sum memory or alibi memory).
	ALB.SHW (Alibi Show)	EDIT.AB (Edit Alibi Number) "000000" // 0 flashing --> Selection of the alibi entry.	Show alibi entry (show a specific weight value saved in the sum memory).
	GET.LST (Get Last Alibi Number) (Number of Entries)	"0" // the number of values saved in the sum memory	
	TAC (Tac counter)	"0" // Number of the executed calibration processes (or number of the storage processes in the menu protected by a password).	
CODE		"- - -" flashing --> CODE = 0000	Change-over to the "Menu protected by a password".

8.3 Menu protected by a password

- Activation of the main menu
- Navigation to "CODE"
- Enter CODE = 0000 using the keys <UP> and <LEFT> and confirm with <ENTER>

Menu	Subroutine	Options	Function
SETTING	DEC 1	0.0, 0.00, 0.000, 0.0000,	Setting of the desired number of digits after the decimal point.
	INC	1, 2, 5, 10, 20, 50, 100, 200	Increments for the displayed weight (resolution).
	CAP	"00.0000" flashing --> Enter the value using the keys <UP> and <LEFT>	Setting of the maximum capacity.
	OLP	On	"—OVL—" appears when the max. capacity is exceeded.
		Off	Output of the current weight, even if the max. capacity has been exceeded.
	ULP	On	"—UVL—" appears when the min. capacity is gone below.
		Off	Output of the current weight, even if the min. capacity has been gone below.
RnIn	Off / Rng / Int	Multi-range / Multi-range scales (is not used!).	

Menu	Subroutine	Options	Function
CAL	SPAN	<p>Raw "000000"</p> <p>Zero "00000" with <ENTER></p> <p>Load "001000" with <UP> and <LEFT> "000000" set the load point with <ENTER></p>	<p>Two-point calibration (zero point, load point)</p> <p>The current ADC value appears.</p> <p>Set zero point</p> <p>Display / setting of load weight</p>

Menu	Subroutine	Options	Function
CAL	mV - V	FIELD	Theoretical calibration.
		<p>Sens "001000" flashing --> Enter the value using the keys <UP> and <LEFT></p> <p>T.CAP flashing --> Enter the value with <UP> and <LEFT></p> <p>Zero "001000" set the zero point with <ENTER></p>	<p>Setting the sensitivity of the load cells used.</p> <p>Setting the maximum load of the load cells used.</p> <p>The current ADC value appears.</p>
		<p>FACTORY (Factory-calibration)</p> <p>SENS "001000" flashing --> Enter the value using the keys <UP> and <LEFT></p> <p>T.CAP flashing --> Enter the value with <UP> and <LEFT></p> <p>Zero "001000" set the zero point with <ENTER></p> <p>Load "000000" set the load point with <ENTER></p>	<p>Theoretical calibration using the load cell simulator.</p> <p>Setting the sensitivity.</p> <p>Setting the maximum load.</p> <p>The current ADC value appears.</p> <p>The current ADC value appears.</p>

Menu	Subroutine	Options	Function
CAL	GrAvtY	“981276” flashing --> Set the gravity value with <UP> and <LEFT>	Adaptation of the gravity factor to correct the weight value on the site of scales use. (Default: 9.8130)
	CAL.SEL	SPAN Calibration method = “Span” FIELD Calibration method = “Field” FACTRY Calibration method = “Factory”	Selection of the active calibration method.
Zero - M		Au.ZERO (Auto Zero) Off / 0.25d / 0.5d / 1d / 2d / 3d / 4d Rn.ZERO (Zero Range) 0, 2, 4, 10, 20, 50, 100 On.ZERO (On Zero) 0, 2, 4, 10, 20, 50, 100	Zero menu Set the range for “Zero_Tracking”. (Zero tracing function). Range, within which the zeroing function can always be carried out (referred in percent to the maximum admissible total weight of the scales). Range, within which the zeroing function can be carried out when the scales is switched on (referred in percent to the maximum admissible total weight of the scales)
Filters	FLT.ACT	On / Off	Filter Active is not used!
RESET		On / Off	Reset to factory-settings

8.4 Quick selection menu (HLG menu)

**Note**

The quick selection menu serves for a facilitated input or reading out parameters and for display parameterisation.

The quick selection menu can be used to set parameters for the function of control weighing cycles, for the alibi memory, the printer, the background lighting and automatic switch-off.

The quick selection menu (while the scales is in weighing mode) can be opened by pressing the key <LEFT> (or <SAVE>) for approx. two seconds.

Menu	Subroutine	Options	Function
HILOGO	HLG.MOD (High-Low-Go - Mode)	Off = three-colour light is deactivated 3-colour = 3-colour mode for the sorting lights 4-colour = 4-colour mode for the sorting lights	Settings for the sorting lights.
	BEEP	Off = acoustic signal deactivated Be OK = acoustic signal in the "Green area" Be Lo = acoustic signal in the "Yellow area" Be Hi = acoustic signal in the "Red area" Be HiLo = acoustic signal in the "Yellow area" and the "Red area" Be OVL = acoustic signal for overload or underload.	Additional acoustic function for the sorting lights (referred to the HLG mode = 3rd colour)
	STORE	On = The HLG limit values are saved. Off = HLG limit values must be set again after a power reset.	Saving the HLG limit values.
	BRIGHT (Brightness)	"Brl.000" flashing --> Enter the value using the keys <UP> and <LEFT> Brightness 0 - 100 %	Settings for the brightness of the sorting light LEDs. The brightness is subdivided in 32 stages and a change is visible each 3-4 %.

Menu	Subroutine	Options	Function
DISPL	B.Light (Backlight)	<p>BI AU (Backlight Auto) 10 / 20 / 30 / 40 / 50 / 60 / 70 / 80 / 90 / 100 / 110 / 120 --> Set the value with <UP></p> <p>BI On = Background lighting always ON. BI Off = Background lighting always OFF.</p>	<p>Settings for the display (background lighting)</p> <p>Automatic activation / switch-off of the background lighting after N seconds. The background lighting is automatically activated when the weight changes or a key is pressed.</p>
	AU OFF	<p>"AU 00" flashing --> Enter the time (minutes) using <UP> and <LEFT> and confirm with <ENTER>.</p> <p>0 - 99 Value "00" = no switch-off</p>	<p>Automatic switch-off of the scales, if no key is actuated and the weight does not change.</p>
	LNG (Language)	<p>ENG = "G" GEr = "B"</p>	<p>The symbol for gross appears as "G" or "B" on the display.</p>

9 Declaration of Conformity

9.1 Declaration of Conformity for non-verified scales



Bosche GmbH & Co. KG
 Reselager Rieden 3
 D-49401 Damme
 Telefon: 0 54 91 / 999 689 - 0
 Telefax: 0 54 91 / 999 689 - 9
 E-Mail: info@bosche.eu
 Internet: www.bosche.eu

EU-Konformitätserklärung Declaration of conformity • Déclaration de conformité Conformiteitsverklaring • Declaración de conformidad	
Typ / Modell Type / Model • Modèle Model • Tipo / Modelo	Anzeige CSS für nicht selbsttätige, ungeeichte Waagen for non-automatic, non-verified scales pour balances non automatiques et non étalonnées voor niet-automatische, niet-gekalibreerde weegschalen para básculas no automáticas y sin calibrar
Seriennummer siehe Typenschild. For the serial number, see the nameplate. • Pour le numéro de série, voir la plaque signalétique. Voor het serienummer, zie het typeplaatje. • Para el número de serie, consulte la placa de identificación.	
Hersteller Manufacturer • Fabricant Fabrikant • Fabrikante	Bosche GmbH & Co. KG

Die alleinige Verantwortung für die Ausstellung trägt der Hersteller.

The sole responsibility for the issue carries the manufacturer. • La seule responsabilité de l'exposition porte le fabricant. • De verantwoordelijkheid voor de uitgifte draagt de fabrikant. • El único responsable de la publicación lleva el fabricante.

Der oben genannte Gegenstand der Erklärung erfüllt die einschlägigen Harmonisierungsrechtsvorschriften der Union:

The above-mentioned object of the declaration complies with the relevant harmonization legislation of the Union • L'objet de la déclaration susmentionné est conforme à la législation d'harmonisation pertinente de l'Union • Het bovengenoemde voorwerp van de verklaring voldoet aan de relevante harmonisatiewetgeving van de Unie • El objeto de la declaración mencionado anteriormente cumple con la legislación de armonización pertinente de la Unión

2014/35/EU Niederspannungsrichtlinie Low voltage Directive	EN 61010-1:2020 für / for / pour / voor / para 230/115 VAC
2014/30/EU EMV-Richtlinie EMC Directive	EN 55022:2011 EN 61000-6-2:2019 EN 61000-6-4:2019 EN 61000-4-2:2009 EN 61000-4-3:2011 EN 61000-4-4:2012 EN 61000-4-5:2014 EN 61000-4-6:2014
2011/65/EU RoHS	EN IEC 63000:2018

Unterzeichnet für und im Namen von Bosche:

Damme, 07.09.2022

Dipl. Ing. Jarmila Bosche, PhD.
Geschäftsführer • Managing Director
 Directeur général • Directeur • Director general

BOSCHE
WEIGHING SYSTEMS

BOSCHE GmbH & Co. KG
Reselager Rieden 3
49401 Damme
Germany

Tel 05491 999 689 0
Fax 05491 999 689 9
www.bosche.eu
info@bosche.eu